

Inspection Report



73 Twelfth Street Toronto, ON

CONTRACT

TERMS OF INSPECTION....

Address of Service:			
Date of Service:		Weather Conditions:	
Client Name:	X	(hereafter	referred to as the CLIENT)
Mailing Address:	X		
Home Phone:	x Mobile: x	Work Phone:	x
E-Mail:	X	Inspection Fee:	
Closing Date:	X	Payment Method:	□ Cash □ Cheque

The Inspection Company and the CLIENT or the CLIENT's Representative Agree as Follows:

1. THE INSPECTION:

- a. The primary purpose of the Inspection is to help the CLIENT identify major deficiencies of the building.
- b. The Inspection is a general, <u>visual</u> examination and no destructive testing of any kind is performed.
- c. The Inspection is limited to the conditions apparent and existing on the day of the Inspection. Latent defects may not be discovered due to the restrictive nature of a visual inspection as well as any restrictions noted in the Report.
- d. The Inspection meets or exceeds the recognized Standards of Practice of OAHI (Ontario Association of Home Inspectors).
- e. The Inspection is NOT technically exhaustive, and measuring devices may or may not be used.
- f. The Inspector is a building inspection generalist, not acting as a licensed engineer or technician in any trade.
- g. The Inspection is designed to limit the risk of buying a property, but it **cannot eliminate your risk**, nor does the Inspection Company or Inspector assume your risk.
- h. The Inspection is not concerned with aesthetics and minor problems, although some may be noted in the Report.

2. **INSPECTION RESTRICTIONS** (some of these may be included at the discretion of the Inspector, who has final authority)

- a. Any cost estimates for repairs or projected life spans for various aspects of the property are **general and non-binding** they are for the information purposes of the CLIENT only and are not guaranteed or assumed to be entirely accurate.
- b. Any estimates of remaining life span of any component are strictly **estimates, and not guarantees of performance.** Any system may fail prematurely, whether due to abnormal wear, improper maintenance, manufacture or installation, or other unforeseen or indeterminable circumstances.
- c. **Code or ordinance compliance** and/or violations are expressly excluded functionality is the focus. Changes and feasibility of changes to building or property use are outside the scope of the Inspection and Report.
- d. The Inspector does not move any personal property on the premises.
- e. The Inspector will talk about termites and other wood destroying organisms if found, but does not guarantee that they do not exist in hidden areas. A pest control specialist should be consulted.
- f. Air conditioners will not be operated if the temperature has dipped below 12°C or 55°F in the previous 24 hours or if the unit is powered off to prevent damage to the unit.
- g. Furnace heat exchangers cannot be examined in full because they are not completely visible.
- h. The Inspector will not walk about in the attic if it is unsafe to do so or if he determines that damage may result.
- The following are also outside the scope of the Inspection and Report (evaluation by a specialist is recommended):
 - that which is covered, cannot be seen or is not readily accessible, the causes of which include but are not limited to soil, walls, ceilings, floors, carpeting and other flooring materials, furnishings, personal property or any other thing
 - appliances and personal property, both inside and out, including playground equipment
 - structural stability or engineering analysis, geological stability or soils condition, including driveways and sidewalks
 - any aspect, area or component that would be dangerous for the Inspector to inspect
 - no destructive or dangerous probing, dismantling or disassembly
 - **environmental concerns**, including but not limited to asbestos, radon gas, lead paint or lead solder, toxic or flammable chemicals, electromagnetic radiation and water and airborne hazards
 - inspection of detached structures, sheds and/or outbuildings unless specifically included
 - fire protection, fire separations, security and warning systems or devices
 - private water or private sewage systems, water softeners or purifiers, underground wiring and piping
 - tennis courts, pools, spas, saunas, steam baths and related fixtures and equipment
 - wood or gas burning stoves or fireplaces, radio-controlled devices, automatic gates, elevators, lifts, dumbwaiters, solar heating, central vacuum, security alarms, telephone or computer connections and any components thereof
 - reliability and accuracy of thermostatic or time-clock controls
 - efficiency of any system or component, including heat gain/loss analysis.

3. THE REPORT:

- a. The Written Report is not valid unless it is Complete, due to the interconnected nature of building components.
- b. A Complete Written Report consists of this Contract and ALL pages of the Inspection Report, numbered or otherwise, unless a Specialized Service is requested:
- c. The Written Report supersedes any and all other communications, including a Verbal Report.
- d. Any item not specifically referenced in the Written Report is not within the scope of the Inspection.
- e. The Written Report is the **copyrighted work** of the Inspection Company, and the information is for the sole, confidential and exclusive use and possession of the CLIENT. The Written Report may not be re-sold by anyone without written permission from the Inspection Company. Notwithstanding this, the CLIENT absorbs all third-party liability should the CLIENT transfer the Written Report for any reason to any third party. The CLIENT is liable for any breach of this clause and must indemnify the Inspection Company directly in the amount of the original inspection fee or the amount for which the inspection is re-sold, whichever is greater.
- f. The Inspection Company recognizes and permits that the CLIENT may need to provide a copy to the CLIENT's Sales Agent, Lawyer or Banker for the purposes of the current transaction, but this permission terminates upon the Closing Date or upon the CLIENT choosing not to purchase the building. Transfer of any copy to any other party can only be done with permission and notification of the Inspector. Any such copy provided must be a Complete Written Report as defined above in this Contract in order to maintain context and any or all third-party liability is assumed by the CLIENT.

4. THE CLIENT:

- a. The CLIENT acknowledges his/her own **responsibility to understand** the Written Report, whether by asking questions of the Inspector or by third-party translation.
- b. The CLIENT acknowledges that failing to undertake any suggested repair or maintenance, even if relatively minor, may lead to significant and disproportionate repair expenses, and saves the Inspection Company and/or Inspector from any harm or claim as the result of the CLIENT's failure.
- c. If the Inspector recommends that the CLIENT consult with an expert specializing in any given field, the CLIENT must do so at his/her own expense. The CLIENT acknowledges that failure to further investigate may result in significant financial loss to the CLIENT.
- d. After the Inspection date, telephone or e-mail consultation will be available to discuss any aspects of the Report and to discuss possible corrective measures and contractor proposals to repair or improve various building components.
- e. The CLIENT assumes the **risk for all conditions that are concealed from view** at the time of the Inspection and for any items not noted in the Written Report. The CLIENT understands that it is not humanly possible to review a dynamic system such as a building and discover all problems (present and future).
- f. **Duty to Inform** Any claim by the CLIENT with respect to any failures, errors or omissions on the part of the Inspection Company and/or its representatives must be made in writing no more than ten business days after the date of discovery.
- g. Any failure by the CLIENT to notify the Inspection Company as stated above constitutes a waiver of any and all claims for said failure to accurately report the condition in question.
- h. This agreement is binding upon the CLIENT's spouse, heirs, principals, assigns and anyone else who may otherwise claim through the CLIENT.

5. LIMITATIONS OF LIABILITY:

No claim is expressed or given that all problems will be discovered during the course of the inspection.



The Financial Liability of the Inspection Company and/or its agents or employees, shall be **limited to the fee paid** for the Inspection and Report, should the Inspection Company and/or its agents or employees be found liable for any loss or damages resulting from a failure to perform any of its obligations, including but not limited to negligence, tort negligence, breach of contract, or otherwise.

The CLIENT agrees to accept the refund of the fee as full settlement of any and all claims which may ever arise.

- d. Should any individual clause in the Contract be ruled invalid by a Court of Law, the remainder of the Contract is still valid.
- e. **Right to Re-Inspect** The Inspection Company has the Right to Re-Inspect the premises before the CLIENT and/or his agents or independent contractors modify, alter or repair any such items out of which is arising a dispute. The Inspection Company MUST have the opportunity to examine any system or component before it is replaced or repaired to confirm its condition.
- f. The inspection and report are not intended to be used as a guarantee, warranty, insurance policy or certification of any kind, expressed or implied, regarding the adequacy, performance or condition of any inspected structure, item or system.

I have been given the opportunity prior to the inspection to read and clarify this contract, and understand and agree to the above.						
SIGNATURE OF CLIENT or REPRESENTATIVE:	х	REPRESENTATIVE'S PRINTED NAME: (if Client not available)				
INSPECTION COMPANY REPRESENTATIVE:						

13:10 July 10, 2012 73 Twelfth Street Page 1 of 28 info@torontohomeinspections.com 416-694-5859



Table of Contents

Definitions	2	
General Information	2	
Roof	7	
Exterior Surface and Components	8	
Lots and Grounds	10	
Outbuilding	11	
Attic	12	
Structure	13	
Basement	14	
Plumbing	15	
Electrical	16	
Heating System	18	
Air Conditioning	20	
Laundry Room/Area	21	
Kitchen	21	
Bathroom	23	
Interior Space		
Summary		

13:10 July 10, 2012 73 Twelfth Street Page 2 of 28 info@torontohomeinspections.com 416-694-5859



Definitions

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable Functional with no obvious signs of defect.

Marginal Item is not fully functional and requires repair or servicing.

Defective Item needs immediate repair or replacement. It is unable to perform its intended function. Investigate Item not within scope of inspection OR requires specialization OR cannot fully determine its

condition.

Improve Item is acceptable but could be improved, either optionally or when doing other repairs nearby.

Not Inspected Item was not inspected for safety reasons, due to lack of power, or it was inaccessible or

disconnected at time of inspection.

Not Present Item not present or not found.

General Information

Property Information

Note to reader: This report is the result of a visual inspection. The reader is cautioned that the scope of service, terms and conditions of this inspection and report are clearly specified in the signed contract. This inspection is an information session only and is not an express or implied guarantee or warranty. Reliance upon this report by other than the parties to the contract carries significant risk because the written report should be accompanied by a verbal report to clarify context of repairs. Due to the inherent complexity of a building, the reader must assume that not all defects have been found or reported. No third party liability is assumed by the inspection company. This inspection and report are copyrighted work and all relevant rights are reserved. The financial liability of the inspector and/or the inspection company is limited to the fee charged for the service, in any and all cases without exception.

Inspection Date 07/10/2012
Property Address 73 Twelfth Street
City Toronto Prov ON

Client Information

Client Name Chris Taylor Phone 416-707-2680 E-Mail ctaylor@trebnet.com

Inspection Company

Inspector Name Frank Gruszewski

Company Name Blueprint Building Inspections

Address 60 Symons Street

City Toronto State ON Zip M8V 1T9 Company Phone 416-694-5859 Fax

Company E-Mail info@torontohomeinspections.com

File Name 20120710-10-12th

Conditions

13:10 July 10, 2012 73 Twelfth Street Page 3 of 28 info@torontohomeinspections.com 416-694-5859



General Information (Continued)

Agent -

For Purposes of Inspection, Entrance Faces West Electric On Yes Gas/Oil On Yes Water On Yes Space Below Grade Basement Estimated Age less than 5 Garage Attached

Introduction to Our Service -

SUPPORT

Blueprint Building Inspections provides building inspection and information services designed to give you as much information as possible, in order to assist you to be completely comfortable in your new property.

One thing we have been stressing since 1995 is that our service does not end on the day of the inspection. We are available to you hours, days, weeks, months or even years after the inspection.

There are two ways to get help after the inspection - by phone or by web. There is an e-mail submission form on our website at www.torontohomeinspections.com, or you can e-mail us at info@torontohomeinspections.com. Our toll-free number is 1-888-812-5552.

WHAT TO EXPECT

The intent of our service is twofold: to provide you, the prospective property owner, with information about buildings in general and this house in particular; and to detect and identify major problems with the building.

The inspection Blueprint will be providing for you today is a visual inspection. The report is the opinion of the individual inspector based on his/her experience and knowledge of construction practices and building operation. The inspection is intended to be a comprehensive overview of the primary structure of the property and is not, and should not be considered, an exhaustive detailed inspection of each system and component. This service is designed to meet the standard for professional building inspections set by the Canadian Association of Home and Property Inspectors.

A building inspection is designed to better your odds, it cannot eliminate all risk of buying a building. Some problems will only occur intermittently (for example, during seasonal changes, when the wind is blowing from a specific direction, etc.). Others may only occur when the property is occupied and actively used (for example, a shower may not show evidence of a leak if used infrequently, but when used regularly a leak may become quite apparent).

Minor problems detected while inspecting for major problems will be noted as a courtesy, but should not be considered an integral part of the inspection. Blueprint's service is informational in nature and in no way is a guarantee or warranty on the building or its systems and components. Warranties can be purchased independently and we suggest you further investigate

Palm-Tech Inspector, Copyright © 1998-2012, PDmB, Inc.

13:10 July 10, 2012 73 Twelfth Street Page 4 of 28 info@torontohomeinspections.com 416-694-5859



General Information (Continued)

the products available if this is what you are looking for.

The inspection is not an inspection for code conformance or bylaw compliance. While some of the defects included in the report may, in fact, be code issues, they are generally only included if they affect the safety and/or habitability of the building. It is not possible to tell which code was in force at the time of the work. A 25 year old house in original condition may be operating quite acceptably and be perfectly safe, however, would not conform to current codes. Also, different municipalities have variations in codes and bylaws.

It has been estimated that there are approximately 3 million symptoms, clues and items that can be found in a building. With all of these variables it would be impossible for any individual to find and take into consideration every one within the scope of a visual inspection. Therefore, there will be areas where Blueprint will not make a definitive statement. For example, the inspector cannot:

- Predict the future behaviour of systems and components of the building. If there are no visible clues to indicate a past problem, it is unfair to assume we should be able to predict a future problem;
- Tell you that water or moisture will never seep into your basement or through your roof coverings;
- Tell you whether mechanical equipment will continue to operate after we leave the property;
- Describe the condition or operation of mechanical components behind walls or in inaccessible areas;
- Tell you that heating and air conditioning equipment will keep you comfortable in all areas of your house in all weather conditions:
- Be assured of the condition of structural components of the building where covered by finishes or inaccessible. There are some things that you can be reasonably assured will happen. For example:
- You will be able to find opinions that differ from those of the inspector:
- You will end up spending money on repairs not noted in the inspection report:
- If you don't inspect and maintain your roof regularly, it will leak; If you don't inspect and maintain the appropriate surface water management systems you will have moisture in your basement area;
- If you don't inspect and maintain caulking and grouting around tubs and tiles on a regular basis you will get leaks at, around and under this area:
- Mechanical items will operate intermittently;
- Problems will not be found or suspected in the absence of symptoms, clues or signs;
- Symptoms, clues and signs are often covered up;
- Some systems and components will operate differently under different weather conditions.

Building Inspectors are generalists in all areas of building construction and building science. As a rule, we do not have specialized knowledge of each area. A useful analogy may be to the medical profession where a general practitioner can give you an overall physical exam, but would not be able to find conditions that did not produce any symptoms or clues. A specialist, on the other hand, may find problems due to his/her specialized knowledge and/or testing procedures.

FOCUS OF INSPECTION

The inspection is focused on the main structural/mechanical systems and components of the primary building, along with areas that could have an impact on the primary building (ex - lot grading, trees, etc).

The inspector assesses the property objectively, inspecting each system and component to determine whether it is performing the basic function for which it was intended. He/she will note any observable major deficiencies that cause the system or component to perform or operate below its intended function. What one person sees as a major problem could be considered as minimally significant to another person, and vice-versa. Further investigation by a specialist may reveal problems or implications not noted by the inspector.

The inspector will take into consideration the age of the system. Older systems may not be performing at the same level of efficiency as when they were new; however, this does not mean they should be considered deficient. Within reasonable levels of tolerances, the inspector will not point out older items that are functioning properly, unless there is a high potential of

13:10 July 10, 2012 73 Twelfth Street Page 5 of 28 info@torontohomeinspections.com 416-694-5859



General Information (Continued)

failure in the near term. While our inspectors are trained in detecting items that are nearing the end of their life cycle or that may fail in the foreseeable future, this inspection is a statement of the condition of the building at the time of the inspection and cannot predict the future.

The opinions expressed by the inspector, both verbally and in writing will have been determined or deduced by what the inspector has observed. It is certainly possible that a current problem does not leave a visible clue. Unless there are substantial and real visible clues, the inspector will generally not provide "could or might" type scenarios. Millions of "what if" scenarios can be proposed and therefore the inspector will generally not initiate "what-if's" but the inspector will discuss them if you ask "what-if".

Most major or significant problems in a building will be accompanied by more than one symptom or clue, therefore, if some are hidden or obstructed, others may be evident.

Except in a limited manner, the inspector will not undertake any destructive or disruptive testing. The inspector will not bore holes in the walls, floors or ceilings, or take core samples of the roof or other material. The inspector's job is to locate or notice as many items as is physically possible by observation, and then deduce conclusions from the total picture.

Where an inspector has indicated an area is restricted, assume it has not been inspected - you are assuming liability for that area.

TWO PASS INSPECTION SYSTEM

Blueprint's inspections are performed in two parts or "passes". On the first pass of the house the inspector will go through and around the house on his/her own, systematically inspecting each of the systems and components covered by the inspection, and simultaneously creating a written report describing their findings.

On the second pass of the house, you will be invited to accompany the inspector through the house while he/she verbally describes their findings. The goal of the second pass is to review the inspector's findings and to give you as much information as possible in the time available to assist you in understanding the building. If you have questions, or there are areas not covered by the inspector, please feel free to ask for clarification or further explanation.

The verbal report is intended to clarify the written report. Also, since verbal communications are subject to each person's interpretation (and even frame of mind), the written report will be considered representative of the inspector's findings. Where there are differences between the written report and what you understand the inspector to have said, we assume you will call Blueprint to achieve a satisfactory clarification.

The purpose of this system is to allow the inspector to focus his/her undivided attention on the house and the report during the first pass and to allow as much time and detail as is necessary to perform a comprehensive inspection. On the second pass, the inspector can focus his/her complete and undivided attention on you, to ensure you have all the information you need to feel comfortable with the decision you make about the house.

Some areas hold more importance than others for different people. Some people hold certain areas to be of the highest importance and significance, while other people will consider an entirely different area to be the most important. Our inspectors will focus their second pass discussions on the areas experience has taught us are generally the most important to most people. However, if an area or item of the house is not given enough time by the inspector relative to its importance to you, or you are unclear of consequences or ramifications, we assume you will ask any and all questions necessary to feel comfortable with that item or area. The inspector will also do his/her best to give you maintenance and repair tips during the second pass. These are given at the inspector's option, time permitting, and are not an integral part of the inspection.

SIGNIFICANT NOTE: Repair/upgrade costs if given are at the discretion of the inspector. The costs given represent, in the opinion of the inspector, the most prudent action. For reasons of personal preference or long term cost effectiveness, you may choose to take actions different from those recommended by the inspector. Further, costs can vary widely depending on numerous factors, including the contractor chosen. For all of the preceding reasons, we strongly recommend confirming all

13:10 July 10, 2012 73 Twelfth Street Page 6 of 28 info@torontohomeinspections.com 416-694-5859



General Information (Continued)

cost estimates with relevant professionals.

YOUR RESPONSIBILITIES

Our goal is to point you in the right direction when we find a defect. We will discuss various methods of repair as time allows, but our primary focus is to help you determine when and who to contact to get more detailed information. There are several ways of approaching each item in need of attention. Repairs can be basic and temporary, or more involved and robust in nature. In some cases, building components can be upgraded. Cost is often a factor.

We have learned over the years that only the new owner can prioritize and undertake repairs, based upon preferences and budget. We would like to hold everyone's hand and make sure all repairs are done diligently, but ultimately the owner is responsible for the care and maintenance of their investment. Make sure that you understand all of the information conveyed to you. Ask questions during the inspection. Review this report as soon as possible and investigate further any areas of uncertainty. Call or email us if you have any questions.

Building Inspectors are generalists in all areas of building construction and building science. As a rule, we do not have specialized knowledge of each area. A useful analogy may be to the medical profession where a general practitioner can diagnose most common ailments, but will refer you to a specialist when more detailed testing and diagnosis is the best course of action.

This report indicates some areas where there is a problem or a potential problem in your building - it does not purport to indicate every problem or potential problem that may exist. Since any of these problems may be more extensive or opinions may differ upon a specialized investigation, we do recommend that you check the opinions in this report with a technician or specialist in the appropriate field, especially where indicated in the report.

Blueprint believes our visual inspection and information service to be quite helpful and useful to prospective building owners, as evidenced from comments from past clients. We endeavor to provide a conscientious, comprehensive and thorough visual inspection. However, we also know that some items may be missed during the inspection. If you are dissatisfied for any reason, we expect that you will communicate any concerns and considerations to us immediately upon discovery so that we can help you. Contact us before making any repairs, with reasonable lead time to allow us to attend the property before commencement of repairs. After a repair has been started it may be impossible to assess the prevailing conditions prior to the repair.

13:10 July 10, 2012 73 Twelfth Street Page 7 of 28 info@torontohomeinspections.com 416-694-5859



Roof

The roof system is evaluated as much as possible, depending upon the restrictions of a visual inspection on the day of the inspection. An estimated age range for roof surfaces is indicated based upon wear patterns of the surfaces. The reader is cautioned that roof surfaces may need replacement years before or after the prediction. In order to properly minimize the risk of leakage, a professional roofer should repair all noted defects. In addition, a roof flashing tune-up should be done every 3 to 5 years to replace worn out caulk and flashings.

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable Functional with no obvious signs of defect.

Marginal Item is not fully functional and requires repair or servicing.

Defective Item needs immediate repair or replacement. It is unable to perform its intended function. Investigate Item not within scope of inspection OR requires specialization OR cannot fully determine its

condition

Improve Item is acceptable but could be improved, either optionally or when doing other repairs nearby.

Not Inspected Item was not inspected for safety reasons, due to lack of power, or it was inaccessible or

disconnected at time of inspection.

Not Present Item not present or not found.

Main Roof Surface

1. Method of Inspection: On roof

2. Acceptable

Material: Asphalt shingle:
Typical wear and tear - expanded seams, edges wearing, minor edge curl, commencement of brittleness, some granules missing exposing substrate of shingle.
Expect replacement in next 4-5 years approximately. Add caulking/tar at front peak shingle over porch where cracked. Keep ivy away from roof line at NE corner



- 3. Type: Hip
- 4. Approximate Age: 10-12 years, (entering last third of life cycle): Most roofs are designed to last 15 years. Note that the age estimate is based upon the appearance of the shingles. They may be older or younger, but the wear patterns indicate the age that was recorded by the inspector.
- 5. Tips We highly recommend a roof and flashing tune-up every 3-5 years as materials such as caulking deteriorate more quickly than other components of the roof.
- 6. Acceptable Wall Flashing: Metal

13:10 July 10, 2012 73 Twelfth Street Page 8 of 28 info@torontohomeinspections.com 416-694-5859



Roof (Continued)

7. Acceptable Valleys: Metal

8. Acceptable
9. Acceptable
10. Acceptable
11. Acceptable
12. Acceptable
13. Acceptable
14. Acceptable
15. Acceptable
16. Acceptable
17. Acceptable
18. Acceptable
19. Stack Flashing: Plastic/rubber
10. Roof Vents: Surface mount
11. Acceptable
12. Acceptable
13. Acceptable
14. Acceptable
15. Acceptable
16. Acceptable
17. Acceptable
18. Acceptable
19. Acceptable
19. Acceptable
19. Acceptable
10. Acceptab

12. Acceptable Mast Flashing: Tar only: Tar/caulk needs regular monitoring to ensure its water integrity

13. Acceptable Gutters: Aluminum14. Acceptable Downspouts: Aluminum

15. Acceptable, Improve Leader/Extension: Extensions, Missing: Damaged extension at NW corner - replace or repair

South Chimney

16. Acceptable Chimney: Brick: Minor tuck point repairs will be needed in next 3-6 years

17. Acceptable Flue/Flue Cap: Clay at top (where visible), Metal liner: Chimney is unused - can be removed when

re-roofing if desired.

18. Acceptable Chimney Flashing: Metal

Exterior Surface and Components

The inspector circles the property at ground level and reports on the visible area of the exterior. The primary considerations are the integrity of the building envelope and structural items, within the scope of a visual inspection. Restrictions such as vegetation, personal property, newer siding, porch and deck structures, snow or even heavy rain may have to be eliminated in order to perform a full evaluation. Any area that is covered or restricted must be disclaimed - the client assumes all risk for hidden areas.

With respect to termites, the inspector pays close attention to all wood to earth close contact, because termites live in the soil and generally forage for food where wood touches the soil. We recommend separation of all wood from the soil by 18 inches and annual investigation. It is also a good idea to check with local pest control specialists to see if they have any history of termite treatment on the property, and to get them to evaluate the property as specialists in the field. The inspector cannot guarantee that no termites are present on the property.

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable Functional with no obvious signs of defect.

Marginal Item is not fully functional and requires repair or servicing.

Defective Item needs immediate repair or replacement. It is unable to perform its intended function. Investigate Item not within scope of inspection OR requires specialization OR cannot fully determine its

condition

Improve Item is acceptable but could be improved, either optionally or when doing other repairs nearby.

Not Inspected Item was not inspected for safety reasons, due to lack of power, or it was inaccessible or

disconnected at time of inspection.

Not Present Item not present or not found.

1. Restrictions: Vegetation, Deck, Porch (underneath),

Main Exterior Surface

2. Acceptable Type: Brick: Tuckpointing required where mortar has cracked in 1-2 areas, Have evaluated/repaired by a masonry specialist in the next few years, Milkbox should be confirmed as being well secured because it

13:10 July 10, 2012 73 Twelfth Street Page 9 of 28 info@torontohomeinspections.com 416-694-5859



Exterior Surface and Components (Continued)

Type: (continued)

is a security risk.

Foundation Exterior Surface •

3. Acceptable Type: Block: Consider, as an upgrade or improvement, adding parging to the foundation to better protect the surface from moisture damage over time.

Windows -

- 4. Acceptable, Improve Window Materials Plastic, Metal: Improve the security at the front sliding windows no locking mechanism
- 5. Acceptable Window Operation Sliders, Hung
- 6. Acceptable Thermal Characteristics Thermal Pane, Single pane: Single pane sliders at front window are less resistant to heat loss than the rest of the windows.
- 7. Acceptable, Improve Window Trim Metal clad: Suggest adding brick moulding or other trim to cover up the expanding foam where visible (at basement windows)
- 8. Acceptable, Marginal Window Sills Jointed, Metal clad, Cementitious: Joints in sills frequently crack and allow moisture to penetrate monitor regularly.

 Suggest minor repair to the basement sills on the driveway side to prevent moisture entry.
- 9. Acceptable Window Wells Metal

Basement (NW) Windows -

- 10. Acceptable Window Materials Wood
- 11. Acceptable Window Operation Awning: Fixed shut
- 12. Marginal Thermal Characteristics Single pane: Single pane windows are not considered thermally efficient by modern standards
- 13. Acceptable Window Trim Wood
- 14. Acceptable Window Sills Wood: Keep well painted and caulked. Consider eventual replacement
- 15. Marginal Fascia: Wood: Some rot in fascia boards suggest replacement but can likely wait until roof is re-shingled.
- 16. Acceptable Soffits: Open framing: At least one or two vents open into attic space, which is good for attic ventilation

13:10 July 10, 2012 73 Twelfth Street Page 10 of 28 info@torontohomeinspections.com 416-694-5859



Exterior Surface and Components (Continued)

17. Acceptable

Entry Doors: Metal: Suggest adding a piece of styrofoam insulation under the side door threshold to reduce heat loss at this location. Side screen door has no self-closer.



18. Acceptable Exterior Lighting: Surface mount

19. Acceptable Hose Bibs: With shutoff, Frost-free: Frost free outlets are much less likely to freeze and burst.

Lots and Grounds

The inspector walked the grounds and made notes with respect to the lot and grounds. However, the only information that is within the scope of the inspection is that which relates directly to the main structure on the property. Information on peripheral items (such as a fence) is presented as a courtesy, but do not assume that these items were inspected in detail - they were given only cursory consideration.

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable Functional with no obvious signs of defect.

Marginal Item is not fully functional and requires repair or servicing.

Defective Item needs immediate repair or replacement. It is unable to perform its intended function.

Investigate Item not within scope of inspection OR requires specialization OR cannot fully determine its

condition.

Improve Item is acceptable but could be improved, either optionally or when doing other repairs nearby. Not Inspected Item was not inspected for safety reasons, due to lack of power, or it was inaccessible or

Treffi was flot inspected for safety reasons, due to lack of power, or it was inaccessible of

disconnected at time of inspection.

Not Present Item not present or not found.

Restrictions: Under deck and porch
 Acceptable Driveway: Gravel

3. Marginal Steps: Wood: Missing handrails (safety, liability) at front porch

4. Acceptable Porch: Wood (over old brick porch)

13:10 July 10, 2012 73 Twelfth Street Page 11 of 28 info@torontohomeinspections.com 416-694-5859



Lots and Grounds (Continued)

5. Acceptable Deck: Wood: Deck constructed on deck blocks - not attached to house - will float up and down on

frost heave so keep water away from it and it should not be too noticeable

6. Acceptable Grading: Minor slope: Ensure grading slopes away from structures. Monitor drainage patterns in heavy rains or during spring thaws to properly assess grading. Lower spots need to be raised up. This is THE most common recommendation that we make.

7. Tips When water or dampness enters a basement, it often started out on the roof. The prevention of rainwater running toward the building at ground level is the first line of defense in protecting against basement seepage. Any areas where water can accumulate or run down the foundation wall should be regraded and sealed so that water extends well away from the building. To allow water to run towards the building is to invite problems.

8. Acceptable Fences: Wood

Outbuilding

Outbuildings (including sheds) are not the focus of this inspection. The primary focus is the main structure on the property. The inspector will inspect any electrical components and note wood to soil contact and wood rot. If a more detailed evaluation of an outbuilding is required, then additional time and thus an additional fee is required.

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable Functional with no obvious signs of defect.

Marginal Item is not fully functional and requires repair or servicing.

Defective Item needs immediate repair or replacement. It is unable to perform its intended function. Investigate Item not within scope of inspection OR requires specialization OR cannot fully determine its

condition.

Improve Item is acceptable but could be improved, either optionally or when doing other repairs nearby. Not Inspected Item was not inspected for safety reasons, due to lack of power, or it was inaccessible or

disconnected at time of inspection.

Not Present Item not present or not found.

Roof Structure: Rafter

1. Restrictions: Locked - no access

Rear Outbuilding -

4. Acceptable

Acceptable Exterior Surface: Wood
 Acceptable Roof: Asphalt shingle

5. Improve Floor: Wood: Wood floor at front (under doors) can allow moisture entry. Investigate adding some

type of flashing options to prevent rot in the future

6. Acceptable Foundation: Block, Deck-Block: Keep water away from the blocks to prevent heave or lifting/settling

of the shed

7. Marginal Doors: Wood: Door needs painting - note the paint is likely to have lead content so be careful and use

appropriate precautions when sanding or scraping.

8. Investigate Electrical: Not visible: Electrical panel indicates there is power to the shed, but shed was locked.

Cannot confirm condition of wiring, Buried wire should be 32" deep and run through conduit or buried under rot resistant boards. There is no way for the inspector to confirm correct burial procedures, so use

caution if any excavation or garden work is undertaken, Confirm electrical is GFCI protected.

13:10 July 10, 2012 73 Twelfth Street Page 12 of 28 info@torontohomeinspections.com 416-694-5859



Outbuilding (Continued)

9. Acceptable, Improve Gutters: Absent: Suggest adding downspouts and eavestroughs to control roof runoff and prevent damage to the outbuilding

Attic

Only portions of the attic are visible. Areas within the attic are restricted from view by the insulation, structural members, irregular attic and roof configurations and poor lighting.

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable Functional with no obvious signs of defect.

Marginal Item is not fully functional and requires repair or servicing.

Defective Item needs immediate repair or replacement. It is unable to perform its intended function. Investigate Item not within scope of inspection OR requires specialization OR cannot fully determine its

condition

Improve Item is acceptable but could be improved, either optionally or when doing other repairs nearby.

Not Inspected Item was not inspected for safety reasons, due to lack of power, or it was inaccessible or

disconnected at time of inspection.

Not Present Item not present or not found.

Attic -

1. Restrictions: 60% visible, Visible from hatch only, Insulation

2. Method of Inspection: From the attic access

3. Acceptable4. Acceptable4. Acceptable7. Roof Framing: Rafter

5. Acceptable Sheathing: Dimensional wood6. Acceptable Ventilation: Roof and soffit vents

7. Improve Insulation: Loose fill cellulose: R20-24 approximate, which is on lower side of acceptable - consider

upgrade.

Insulate and weatherstrip attic hatch to prevent heat and warm air from entering attic

8. Acceptable Vapor Barrier: Plastic below insulation (detected at hatch)

13:10 July 10, 2012 73 Twelfth Street Page 13 of 28 info@torontohomeinspections.com 416-694-5859



Structure

In most cases, there is very little structure visible and this is purely a visual inspection. The structure above the ceiling and behind the walls was not visible. Keep in mind that the location of components, sheer size and number of structural components prevents viewing of them all. The client is assuming the risk of areas hidden from view.

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable Functional with no obvious signs of defect.

Marginal Item is not fully functional and requires repair or servicing.

Defective Item needs immediate repair or replacement. It is unable to perform its intended function.

Investigate Item not within scope of inspection OR requires specialization OR cannot fully determine its

condition.

Improve Item is acceptable but could be improved, either optionally or when doing other repairs nearby.

Not Inspected Item was not inspected for safety reasons, due to lack of power, or it was inaccessible or

disconnected at time of inspection.

Not Present Item not present or not found.

1. Restrictions: 10 % visible, Ductwork, Insulation/vapour retarder, Finishes on ceiling, walls and floor, Storage in furnace area and under stairs

2. Acceptable Structure Type: Masonry: For more information, see the Exterior Surface and Components section.

3. Acceptable, Investigate Foundation: Block: Block foundations are more impervious to water than brick or stone, but

not as good as concrete. Moisture which does enter often does so through the mortar joints. Once moisture does penetrate the block into the cavities within the block, it can take some time before it dries out. Sometimes, a dehumidifier can accelerate this process of drying out if the block is damp. See Basement: humidity readings for more information. Some cracks in block foundation but these are of little consequence, other than the potential for moisture entry. Unfortunately and as is usually the case, the basement is finished so it cannot be confirmed that the cracks are not allowing moisture entry, at least under unusual weather circumstances.

4. Acceptable Beams: Laminated wood

5. Acceptable Joists: 2x8: 2X4 supports are screwed and affixed to joists with adhesive for washroom (over furnace)

- these appear sound.

6. Acceptable Piers/Posts: Masonry pillars

7. Acceptable Floor/Slab: Non-structural concrete

8. Acceptable Floor sheathing: Dimensional wood, Plywood

13:10 July 10, 2012 73 Twelfth Street

Page 14 of 28 info@torontohomeinspections.com 416-694-5859



Basement

In most cases, there is very little structure visible. Wall framing and floor framing on upper floors are inaccessible, and finished basements or storage along walls can be insurmountable restrictions to a visual inspection. Modifications to the structure, such as occurs when walls are removed, are usually hidden by finished surfaces so that the structural members are unseen. The buyer is assuming the risk of areas hidden from view.

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Functional with no obvious signs of defect. Acceptable

Marginal Item is not fully functional and requires repair or servicing.

Defective Item needs immediate repair or replacement. It is unable to perform its intended function. Investigate Item not within scope of inspection OR requires specialization OR cannot fully determine its

Improve Item is acceptable but could be improved, either optionally or when doing other repairs nearby.

Not Inspected Item was not inspected for safety reasons, due to lack of power, or it was inaccessible or

disconnected at time of inspection.

Not Present Item not present or not found.

Basement -

1. Restrictions: See restrictions for Structure

Ceiling: Drywall 2. Acceptable

3. Acceptable Walls: Drywall, Wood

4. Acceptable Floor: Plastic dimpled sub-floor, Wood sub floor, Linoleum/resilient, Laminate: The plastic dimpled

membrane and/or dry-core floor help keep any potential future dampness from impacting negatively

upon the flooring.

5. Investigate Floor Drain: Surface drain: Not visible - confirm location and that it is unblooked

6. Acceptable Electrical: 15 amp 3 prong receptacles, 110 volt lighting circuits

Smoke Detector: Battery operated: Every 7-10 years, manufacturers recommend that new detectors 7. Acceptable

should be installed. Vacuum out intake ports periodically. Suggest CO detector on 1st floor ceiling and/or

outside sleeping areas. Consider interconnected smoke alarms on every level

8. Acceptable HVAC Source: Heating system register

9. Acceptable Insulation: Rockwool batts

Basement Stairs

10. Type Turns and landings

Handrails None: Missing railing, Safety hazard 11. Defective

Average (on foundation at joint between floor and wall) Invasive Testing (Moisture Probe) -

Reading: 10-14%: Moisture readings below 20% are desirable, because mold, mildew and fungi start 12. Acceptable

to grow (especially on wood or cellulose based products) at around the 20% mark. During wet spring conditions, moisture levels can rise. Monitor exterior drainage to ensure that water runs away from foundation.

Peaks, On foundation Invasive Testing(Moisture Probe) -

13. Acceptable, Marginal Reading: 24%: Moisture readings below 20% are desirable, because mold, mildew and fungi start to grow (especially on wood or cellulose based products) at around the 20% mark. During wet spring conditions, moisture levels can rise. Monitor exterior drainage to ensure that water runs away from foundation. The peak readings were recorded on the foundation under the stairs and in a crack by the furnace. There was a musty smell under the stairs (no air flow) and signs of

13:10 July 10, 2012 73 Twelfth Street

Page 15 of 28 info@torontohomeinspections.com 416-694-5859



Basement (Continued)

Reading: (continued)

previous dampness. At a minimum, suggest sealing exposed block with waterproofing paint and use of dehumidifier

Plumbing

As with many building systems, much of the plumbing system is hidden from view. The inspector will operate all fixtures possible and evaluate the visible portions, but problems with venting, leaks or other defects may be discovered after the buyer occupies the property. Even a property that is vacant will restrict the inspector because no current usage pattern exists. We reiterate that the inspection is a visual inspection of all systems on the day of the inspection, and the unique usage patterns of different users may result in the discovery of undetected problems.

Fire protection (and alarm) systems must be inspected as per the requirements of the Fire Code by a certified technician. If the inspector observes any leaks or obvious wiring defects, they will be noted in the report, but this is not the focus of the inspection and the systems must be disclaimed.

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable Functional with no obvious signs of defect.

Marginal Item is not fully functional and requires repair or servicing.

Defective Item needs immediate repair or replacement. It is unable to perform its intended function. Item not within scope of inspection OR requires specialization OR cannot fully determine its Investigate

condition.

Item is acceptable but could be improved, either optionally or when doing other repairs nearby. Improve Not Inspected Item was not inspected for safety reasons, due to lack of power, or it was inaccessible or

disconnected at time of inspection.

Item not present or not found. Not Present

1. Restrictions: Throughout all buildings, wall and ceiling finishes restrict complete evaluation - hidden defects usually go undetected during inspections

Service Line: Lead: Lead supply pipes should be flushed in morning for a moment before drinking 2. Acceptable water, and also restrict water pressure.

Main Water Shutoff: Basement (front) 3. Acceptable

Water Lines: Copper 4. Acceptable

Drain Pipes: ABS, Lead, Cast iron 5. Acceptable

6. Investigate Exterior Service Caps: Not visible: The presence or absence of exterior drain access caps may

mean that the vent pipe was removed, or it may mean nothing. Check with public works to see what

work has been done under permit and to find out if any work is recommended

Vent Pipes: ABS, Cast iron: Venting refers to the introduction of air from above a fixture. All fixtures 7. Acceptable

should eventually connect to the plumbing stack on the roof so that atmospheric pressure can help push water down the drain, so that methane gas is vented harmlessly to the exterior, and so that air can be introduced into the drain lines to prevent a vacuum that can inadvertently suck a trap dry as water

rushes past from another draining fixture (Bernoulli Principle).

13:10 July 10, 2012 73 Twelfth Street

Page 16 of 28 info@torontohomeinspections.com 416-694-5859



Plumbing (Continued)

Basement, Furnace area Water Heater

Water Heater Operation: Functional at time of inspection: We suggest that you drain out a bucket 8. Acceptable of water from the drain valve on the water heater whenever you change your furnace filter. This will help cut down on sediment which will help maintain the unit's efficiency and lifespan. You will also notice any changed in water quality that would signal a need for service by a certified technician.

9. Type: Electric Capacity: 60 US Gal = 227 Litres

10. Approximate Age: 5 or 10 (ambiguous serial number) Area Served: Whole building

TPRV and Drain Tube: Brass valve, CPVC tube 11. Acceptable

Electrical

The electrical system is largely hidden, and visible defects are noted. A number of visible defects often means that there are more defects that are not visible. Other issues, such as type of wiring, are spoken of in general terms in addition to any noted repairs. It is recommended that a licensed electrician conduct the repairs and further evaluate the system.

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Functional with no obvious signs of defect. Acceptable

Marginal Item is not fully functional and requires repair or servicing.

Defective Item needs immediate repair or replacement. It is unable to perform its intended function. Item not within scope of inspection OR requires specialization OR cannot fully determine its Investigate

Item is acceptable but could be improved, either optionally or when doing other repairs nearby. Improve Not Inspected Item was not inspected for safety reasons, due to lack of power, or it was inaccessible or

disconnected at time of inspection.

Item not present or not found. Not Present

- 1. Restrictions: Throughout all buildings, wall and ceiling finishes restrict complete evaluation hidden defects usually go undetected during inspections
- 2. Service Size Amps: 100
- 3. Acceptable Service: Overhead
- 4. Acceptable 120 VAC Branch Circuits: Copper
- 240 VAC Branch Circuits: Copper 5. Acceptable
- 6. Acceptable Conductor Type: BX (armoured cable), NMD-90 (Romex), NMD-3 or 7 (Loomex)
- 7. Acceptable Ground: Plumbing ground

Basement (north) Electric Panel -

- Manufacturer: Siemens 8. Acceptable
- 9. Maximum Capacity: 125 Amps
- 10. Acceptable Main Disconnect Size: 100 Amps
- 11. Acceptable, Defective Breakers: 15, 20, 30, 40 amps: A/C disconnect is 30 amp, but a/c data label states max of 15 amp - replace breaker with double pole 15 amp breaker
- 12. Acceptable AFCI: 110 volt: Arc Fault Circuit Interrupters are used in bedroom circuits to ward off fires. Push test button every month or two to test circuitry. To reset, shut breaker switch all the way off and on. Now reset your clock radios.

13:10 July 10, 2012 73 Twelfth Street Page 17 of 28 info@torontohomeinspections.com 416-694-5859



Electrical (Continued)

13. Marginal

Electrical defects Furnace utility room: Cap off unterminated wire under bathroom floor - should terminate in a box.



14. Marginal

Electrical defects Kitchen: Wire feeding light over sink is exposed and technically should be run through conduit. However this is a low risk issue.



13:10 July 10, 2012 73 Twelfth Street Page 18 of 28 info@torontohomeinspections.com 416-694-5859



Heating System

The visual inspection of a heating system will include operation of the unit if it can safely be done. Age estimates are determined by appearance and decoding of serial numbers, unless the actual date of manufacture is visible on the unit. The age estimate should be considered a best guess, and the recommended course of action for the buyer is to contact the manufacturer with the model and serial number to confirm the age of the system. Finally, keep in mind that a furnace is a machine, and can break down at any time.

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable Functional with no obvious signs of defect.

Marginal Item is not fully functional and requires repair or servicing.

Defective Item needs immediate repair or replacement. It is unable to perform its intended function.

Investigate Item not within scope of inspection OR requires specialization OR cannot fully determine its

condition

Improve Item is acceptable but could be improved, either optionally or when doing other repairs nearby.

Not Inspected Item was not inspected for safety reasons, due to lack of power, or it was inaccessible or

disconnected at time of inspection.

Not Present Item not present or not found.

1. Restrictions: Sealed combustor - heat exchanger is 0% visible

Basement Heating System -

2. Acceptable, Defective Heating System Operation: Appears functional: Consult a heating technician to develop an annual maintenance program to maximize the life of the unit.

Defective note: Correct the electrical connection where the armoured cable connects to the

furnace - improper connection.

3. Manufacturer: Goodman

4. Type: Forced air Capacity: 64.4 kbtu/hr

5. Area Served: Whole building Approximate Age: 5

6. Fuel Type: Natural gas

7. Acceptable Heat Exchanger: Sealed primary and secondary heat exchanger

8. Acceptable Blower Fan: Below heat exchanger

9. Acceptable, Improve Air Filter 4" pleated disposable: It appears the air filter, while of high quality, may not be tight

enough and air is likely escaping around the edges. Consult your HVAC contractor to correct this

 $minor\ is sue.$

10. Acceptable Distribution: Metal duct11. Acceptable Draft Control: Motor driven

13:10 July 10, 2012 73 Twelfth Street Page 19 of 28 info@torontohomeinspections.com 416-694-5859



Heating System (Continued)

12. Improve

Flue Pipe: White plastic (class IIA gas vent): Turn the top elbow of the exhaust duct away from the brick face. Note the moisture stains on the brick now - this pattern will eventually show up as a wear pattern on the brick and mortar.

Monitor interior rubber fitting to ensure no liquid condensate or flue gases are leaking.





13. Acceptable Thermostats: Programmable

14. Suspected Asbestos: No

13:10 July 10, 2012 73 Twelfth Street Page 20 of 28 info@torontohomeinspections.com 416-694-5859



Air Conditioning

The visual inspection of an air conditioning system will include the operation of the unit if the exterior temperature has been above 15 degrees Celsius for the last 24 hours. Age estimates are determined by appearance and decoding of serial numbers, unless the actual date of manufacture is visible on the unit. The age estimate should be considered a best guess, and the recommended course of action for the buyer is to contact the manufacturer with the model and serial number to confirm the age of the system. We recommend that the unit be examined/serviced by a licensed contractor in the first year of building ownership to get a complete picture of its operation. Finally, keep in mind that an air conditioner compressor is a machine, and can break down at any time.

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable Functional with no obvious signs of defect.

Marginal Item is not fully functional and requires repair or servicing.

Defective Item needs immediate repair or replacement. It is unable to perform its intended function. Investigate Item not within scope of inspection OR requires specialization OR cannot fully determine its

condition.

Improve Item is acceptable but could be improved, either optionally or when doing other repairs nearby. Not Inspected Item was not inspected for safety reasons, due to lack of power, or it was inaccessible or

therm was not inspected for safety reasons, due to lack of power, or it was maccessible

disconnected at time of inspection.

Not Present Item not present or not found.

Exterior AC System

1. Acceptable A/C System Operation: Functional: Expected life span in our area is +-15 years. A qualified air conditioning contractor is recommended to evaluate and do annual maintenance on system to gain more information on its condition and performance.

2. Acceptable Condensate Removal: Electric pump, Laundry tub

3. Acceptable Exterior Unit: Pad mounted

4. Manufacturer: Goodman

5. Area Served: Whole building Approximate Age: 4

6. Type: 220 volt electric Capacity: 1.5 Ton

7. RLA 8.9 Max Fuse Capacity 15 amp

8. Acceptable Visible Coil: Copper core with aluminum fins

9. Acceptable Refrigerant Lines: Low pressure and high pressure10. Acceptable Electrical Disconnect: Exterior weatherproof box

Air Filter Same as heating system filter - See Heating Section: As a matter of good maintenance, we recommend checking the air filter monthly and cleaning or replacing as necessary. Change filter regularly in cooling season also. An ineffective filter will allow accumulation of dust on evaporator coil, and will lower cooling effectiveness and possibly lifespan of system. If cleanliness of evaporator in ductwork is

questionable, consider having the system cleaned by a certified technician.

13:10 July 10, 2012 73 Twelfth Street

Page 21 of 28 info@torontohomeinspections.com 416-694-5859



Laundry Room/Area

The area was examined for leaks, damage and, symptoms of structural problems. Cosmetic issues are of no concern to the inspector, even though they may be important to the purchaser (and expensive to change/repair). Components of systems such as heating or electrical are also inspected.

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Functional with no obvious signs of defect. Acceptable

Marginal Item is not fully functional and requires repair or servicing.

Item needs immediate repair or replacement. It is unable to perform its intended function. Defective Investigate Item not within scope of inspection OR requires specialization OR cannot fully determine its

condition.

Item is acceptable but could be improved, either optionally or when doing other repairs nearby. Improve

Not Inspected Item was not inspected for safety reasons, due to lack of power, or it was inaccessible or

disconnected at time of inspection.

Not Present Item not present or not found.

1. Restrictions: Wall finishes and laundry appliances themselves

Basement Laundry Room/Area -

2. Acceptable Laundry Tub: PVC

Laundry Tub Faucet: No shutoffs 3. Acceptable 4. Acceptable Laundry Tub Drain: ABS plastic 5. Acceptable Washer Hose Bib: Ball valves

Washer and Dryer Electrical: 110-220 VAC: Where it exits the wall, protect the wire feeding the 6. Acceptable

dryer plug from physical damage - minor note

Dryer Vent: Metal flex, Rigid metal: Clean annually, Suggest a different type of exterior vent cover as 7. Acceptable

the grill will catch more lint than desirable.

Washer Drain: Wall mounted drain 8. Acceptable

Kitchen

The area was examined for leaks, damage or symptoms of structural problems. Cosmetic issues are of no concern to the inspector, even though they may be important to the purchaser (and expensive to change/repair). Components of systems such as heating or electrical are also inspected.

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable Functional with no obvious signs of defect.

Item is not fully functional and requires repair or servicing. Marginal

Item needs immediate repair or replacement. It is unable to perform its intended function. Defective Item not within scope of inspection OR requires specialization OR cannot fully determine its Investigate

Item is acceptable but could be improved, either optionally or when doing other repairs nearby. Improve Not Inspected Item was not inspected for safety reasons, due to lack of power, or it was inaccessible or

disconnected at time of inspection.

Item not present or not found. Not Present

13:10 July 10, 2012 73 Twelfth Street Page 22 of 28 info@torontohomeinspections.com 416-694-5859



Kitchen (Continued)

1. Restrictions: Typical restrictions - finishes on walls, ceiling, floors and storage in cupboards, as well as appliances themselves

1st Floor Kitchen

2. Acceptable Ventilation: Over the stove fan - vented to exterior

3. Acceptable Sink: Fiberglass or similar

4. Acceptable Electrical: 20 amp GFCI circuits

5. Acceptable Faucets: No shutoffs
6. Acceptable Traps: Trap has cleanout
7. Acceptable, Improve Counter Tops: Wood

butcher block: Suggest caulk at wood counter joint

against wall.



8. Acceptable
9. Acceptable
10. Acceptable
Receptable
Ceiling: Drywall
Walls: Drywall, Wood
Floor: Ceramic tile

13:10 July 10, 2012 73 Twelfth Street Page 23 of 28 info@torontohomeinspections.com 416-694-5859



Bathroom

The area was examined for leaks, damage or structural problems. Cosmetic issues are of no concern to the inspector, even though they may be important to the purchaser (and expensive to change/repair). Components of systems such as heating or electrical are also inspected.

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable Functional with no obvious signs of defect.

Marginal Item is not fully functional and requires repair or servicing.

Defective Item needs immediate repair or replacement. It is unable to perform its intended function.

Investigate Item not within scope of inspection OR requires specialization OR cannot fully determine its

condition.

Improve Item is acceptable but could be improved, either optionally or when doing other repairs nearby.

Not Inspected Item was not inspected for safety reasons, due to lack of power, or it was inaccessible or

disconnected at time of inspection.

Not Present Item not present or not found.

1. Restrictions: Typical restrictions - finishes on walls, ceiling, floors and storage in cupboards

Basement (toilet only) Bathroom -

2. Acceptable Toilets: 6.0 lpf, Lined tank

1st floor Bathroom

Acceptable Ceiling: Drywall/plaster
 Acceptable Walls: Drywall/plaster, Wood

5. Acceptable Floor: Ceramic tile6. Acceptable Doors: Hollow

7. Acceptable Electrical: 110 VAC outlets and lighting circuits, GFCI protected receptacle

8. Acceptable Sink/Basin: Pedestal9. Acceptable Faucets: No shutoffs

10. Acceptable Traps: Trap can be opened (locknuts)

11. Acceptable Tub/Surround: Fiberglass surround and tub insert

12. Acceptable Toilets: Lined tank, 6.0 lpf

13. Acceptable HVAC Source: Heating system register

14. Marginal Ventilation: Window: Consider exhaust fan, ensuring it is vented to exterior

13:10 July 10, 2012 73 Twelfth Street Page 24 of 28 info@torontohomeinspections.com 416-694-5859



Interior Space

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable Functional with no obvious signs of defect.

Marginal Item is not fully functional and requires repair or servicing.

Defective Item needs immediate repair or replacement. It is unable to perform its intended function.

Investigate Item not within scope of inspection OR requires specialization OR cannot fully determine its

condition.

Improve Item is acceptable but could be improved, either optionally or when doing other repairs nearby.

Not Inspected Item was not inspected for safety reasons, due to lack of power, or it was inaccessible or

disconnected at time of inspection.

Not Present Item not present or not found.

1. Restrictions: Typical restrictions - finishes on walls, ceiling, floors and storage in cupboards, Furniture

1st floor Interior Space

Acceptable Ceiling: Drywall/plaster
 Acceptable Walls: Drywall/plaster

4. Acceptable Floor: Ceramic tile, Linoleum/resilient

5. Acceptable Floor: Hardwood: Hardwood manufacturers recommend 40-50% humidity in winter to prevent

shrinkage. This higher humidity can reduce indoor air quality. Use a hygrometer to strike a balance so that windows and walls do not collect condensation. Keep blinds open slightly for the same reason. If condensation occurs persistently through the winter, an HVI certified HRV (Heat Recovery Ventilator)

should be considered.

6. Acceptable Electrical: 15 amp 3 prong (110 volt) receptacles, 110 volt lighting circuits

7. Acceptable HVAC Source: Heating system register

8. Acceptable Smoke Detector: Battery operated: Every 7-10 years, manufacturers recommend that new detectors

should be installed. Vacuum out intake ports periodically. Suggest CO detector on 1st floor ceiling and/or

outside sleeping areas. Consider interconnected smoke alarms on every level

Final Comments

The house is solid structurally and the items noted in this report are common in older homes. The house compares favourably with other homes in this age range, and the repairs/improvements conducted in the last few years have been done well. Continue to improve/repair, using this report as a guideline.

13:10 July 10, 2012 73 Twelfth Street Page 25 of 28 info@torontohomeinspections.com 416-694-5859



Marginal Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Exterior Surface and Components

Windows Window Sills Jointed, Metal clad, Cementitious: Joints in sills frequently crack and allow moisture to penetrate - monitor regularly.

Suggest minor repair to the basement sills on the driveway side to prevent moisture entry.

Basement (NW) Windows Thermal Characteristics Single pane: Single pane windows are not considered thermally efficient by modern standards

Fascia: Wood: Some rot in fascia boards - suggest replacement but can likely wait until roof is re-shingled.

Lots and Grounds

Steps: Wood: Missing handrails (safety, liability) at front porch

Outbuilding

Rear Outbuilding Doors: Wood: Door needs painting - note the paint is likely to have lead content so be careful and use appropriate precautions when sanding or scraping.

Basement

Peaks, On foundation Invasive Testing(Moisture Probe) Reading: 24%: Moisture readings below 20% are desirable, because mold, mildew and fungi start to grow (especially on wood or cellulose based products) at around the 20% mark. During wet spring conditions, moisture levels can rise. Monitor exterior drainage to ensure that water runs away from foundation. The peak readings were recorded on the foundation under the stairs and in a crack by the furnace. There was a musty smell under the stairs (no air flow) and signs of previous dampness. At a minimum, suggest sealing exposed block with waterproofing paint and use of dehumidifier

Electrical

Electrical defects Furnace utility room: Cap off unterminated wire under bathroom floor - should terminate in a box. Electrical defects Kitchen: Wire feeding light over sink is exposed and technically should be run through conduit. However this is a low risk issue.

Bathroom

1st floor Bathroom Ventilation: Window: Consider exhaust fan, ensuring it is vented to exterior

13:10 July 10, 2012 73 Twelfth Street Page 26 of 28 info@torontohomeinspections.com 416-694-5859



Defective Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Basement

Basement Stairs Handrails None: Missing railing, Safety hazard

Electrical

Basement (north) Electric Panel Breakers: 15, 20, 30, 40 amps: A/C disconnect is 30 amp, but a/c data label states max of 15 amp - replace breaker with double pole 15 amp breaker

Heating System

Basement Heating System Heating System Operation: Appears functional: Consult a heating technician to develop an annual maintenance program to maximize the life of the unit.

Defective note: Correct the electrical connection where the armoured cable connects to the furnace - improper connection.

13:10 July 10, 2012 73 Twelfth Street Page 27 of 28 info@torontohomeinspections.com 416-694-5859



Investigate Summary

These items could not be inspected adequately and require further action to fully determine their condition. This may include destructive testing, scientific analysis or the services of a licensed specialist.

Outbuilding

Rear Outbuilding Electrical: Not visible: Electrical panel indicates there is power to the shed, but shed was locked. Cannot confirm condition of wiring, Buried wire should be 32" deep and run through conduit or buried under rot resistant boards. There is no way for the inspector to confirm correct burial procedures, so use caution if any excavation or garden work is undertaken, Confirm electrical is GFCI protected.

Structure

Foundation: Block: Block foundations are more impervious to water than brick or stone, but not as good as concrete. Moisture which does enter often does so through the mortar joints. Once moisture does penetrate the block into the cavities within the block, it can take some time before it dries out. Sometimes, a dehumidifier can accelerate this process of drying out if the block is damp. See Basement: humidity readings for more information. Some cracks in block foundation but these are of little consequence, other than the potential for moisture entry. Unfortunately and as is usually the case, the basement is finished so it cannot be confirmed that the cracks are not allowing moisture entry, at least under unusual weather circumstances.

Basement

Basement Floor Drain: Surface drain: Not visible - confirm location and that it is unblcoked

Plumbing

Exterior Service Caps: Not visible: The presence or absence of exterior drain access caps may mean that the vent pipe was removed, or it may mean nothing. Check with public works to see what work has been done under permit and to find out if any work is recommended

13:10 July 10, 2012 73 Twelfth Street Page 28 of 28 info@torontohomeinspections.com 416-694-5859



Improve Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Roof

Leader/Extension: Extensions, Missing: Damaged extension at NW corner - replace or repair

Exterior Surface and Components

Windows Window Materials Plastic, Metal: Improve the security at the front sliding windows - no locking mechanism Windows Window Trim Metal clad: Suggest adding brick moulding or other trim to cover up the expanding foam where visible (at basement windows)

Outbuilding

Rear Outbuilding Floor: Wood: Wood floor at front (under doors) can allow moisture entry. Investigate adding some type of flashing options to prevent rot in the future

Rear Outbuilding Gutters: Absent: Suggest adding downspouts and eavestroughs to control roof runoff and prevent damage to the outbuilding

Attic

Attic Insulation: Loose fill cellulose: R20-24 approximate, which is on lower side of acceptable - consider upgrade. Insulate and weatherstrip attic hatch to prevent heat and warm air from entering attic

Heating System

Basement Heating System Air Filter 4" pleated disposable: It appears the air filter, while of high quality, may not be tight enough and air is likely escaping around the edges. Consult your HVAC contractor to correct this minor issue.

Basement Heating System Flue Pipe: White plastic (class IIA gas vent): Turn the top elbow of the exhaust duct away from the brick face. Note the moisture stains on the brick now - this pattern will eventually show up as a wear pattern on the brick and mortar.

Monitor interior rubber fitting to ensure no liquid condensate or flue gases are leaking.

Kitchen

1st Floor Kitchen Counter Tops: Wood butcher block: Suggest caulk at wood counter joint against wall.